

Data/ora deconectarii	Data/ora conectarii	Adresa deconectării	Denumirea PT	Denumirea lucrarilor	LEA/PT
2022-05-10 8:00	2022-05-10 16:00	sat Drochia	PT72SUR8	Reparatia curente	LEA 0.4 KV
2022-05-10 8:00	2022-05-10 16:00	sat Zgurița	PT251ZG15F1	Reparatia curente	LEA 0.4 KV
2022-05-10 8:00	2022-05-10 16:00	sat Zgurița	PT251ZG15F2	Reparatia curente	LEA 0.4 KV
2022-05-10 8:00	2022-05-10 16:00	sat Moara de Piatră	PT40ND5	Reparatia curente	PT-10/0.4 KV
2022-05-10 8:00	2022-05-10 16:00	sat Moara de Piatră	PT49ND5	Reparatia curente	PT-10/0.4 KV
2022-05-11 8:00	2022-05-11 16:00	sat Drochia	PT73SUR8	Reparatia curente	LEA 0.4 KV
2022-05-11 8:00	2022-05-11 16:00	sat Zgurița	PT252ZG15	Reparatia curente	LEA 0.4 KV
2022-05-11 8:00	2022-05-11 16:00	sat Moara de Piatră	PT291ND5	Reparatia curente	PT-10/0.4 KV
2022-05-11 8:00	2022-05-11 16:00	sat Moara de Piatră	PT326ND5	Reparatia curente	PT-10/0.4 KV
2022-05-12 8:00	2022-05-12 16:00	sat Drochia	PT71SUR8	Reparatia curente	LEA 0.4 KV
2022-05-12 8:00	2022-05-12 16:00	sat Zgurița	PT399ZG15F1	Reparatia curente	LEA 0.4 KV
2022-05-12 8:00	2022-05-12 16:00	sat Zgurița	PT409ZG16F1	Reparatia curente	LEA 0.4 KV
2022-05-12 8:00	2022-05-12 16:00	sat Moara de Piatră	PT36ND5	Reparatia curente	PT-10/0.4 KV
2022-05-12 8:00	2022-05-12 16:00	sat Moara de Piatră	PT48ND5	Reparatia curente	PT-10/0.4 KV
2022-05-12 8:00	2022-05-12 16:00	sat Zgurița	PT399ZG15F2	Reparatia curente	LEA 0.4 KV
2022-05-13 8:00	2022-05-13 16:00	sat Hăsnășenii Mari	PT35ND5	Reparatia curente	PT-10/0.4 KV
2022-05-13 8:00	2022-05-13 16:00	sat Drochia	PT194SUR8	Reparatia curente	LEA 0.4 KV
2022-05-13 8:00	2022-05-13 16:00	sat Zgurița	PT454ZG15	Reparatia curente	LEA 0.4 KV
2022-05-13 8:00	2022-05-13 16:00	sat Hăsnășenii Mari	PT311ND5	Reparatia curente	PT-10/0.4 KV