

Data/ora deconectării	Data/ora conectării	Adresa deconectării	Denumirea PT	Denumirea lucrarilor	LEA/PT
2022-05-10 8:00	2022-05-10 16:00	S,PIRLITA	PT574PR7F1	Strunirea conductorilor	LEA 0.4 KV
2022-05-10 8:00	2022-05-10 16:00	S,COSTULENI PARTIAL	PT266VM14	Schimbarea stilpilor	LEA 10KV
2022-05-10 8:00	2022-05-10 16:00	S,COSTULENI PARTIAL	PT282VM14	Schimbarea stilpilor	LEA 10KV
2022-05-10 8:00	2022-05-10 16:00	STR,,AL.CEL.BUN,DECEBAL,G MENIUC,M SADOVEANU,M VITEAZUL	PT25UN26	Reparatia curente	PT-10/04(tip inchis)
2022-05-10 8:00	2022-05-10 16:00	,AL.CEL.BUN,DECEBAL,G MENIUC,M SADOVEANU,M VITEAZUL,O U	PT25UN26F5	Reparatia curente	LEC 0.4 KV
2022-05-10 8:00	2022-05-10 16:00	,AL.CEL.BUN,DECEBAL,G MENIUC,M SADOVEANU,M VITEAZUL,O U	PT25UN26F8	Reparatia curente	LEC 0.4 KV
2022-05-10 8:00	2022-05-10 16:00	S,CIOROPCANI	PT375CP5F1	Efectuarea masurarilor	LEA 0.4 KV
2022-05-10 8:00	2022-05-10 16:00	S,CIOROPCANI	PT375CP5F2	Efectuarea masurarilor	LEA 0.4 KV
2022-05-11 8:00	2022-05-11 16:00	S,PIRLITA	PT528PR10F2	Strunirea conductorilor	LEA 0.4 KV
2022-05-11 8:00	2022-05-11 16:00	S,PIRLITA	PT528PR10F3	Strunirea conductorilor	LEA 0.4 KV
2022-05-11 8:00	2022-05-11 16:00	S,UNTESTI	PT132DT8F3	Strunirea conductorilor	LEA 0.4 KV
2022-05-11 8:00	2022-05-11 12:00	S,ZAGARANCEA	PT101UN34	Reparatia curente	PT-10/0.4 KV
2022-05-11 8:00	2022-05-11 16:00	S,SEMENI PARTIAL	PT275UN34F3	Montarea prizei de pamint	LEA 0.4 KV
2022-05-11 8:00	2022-05-11 16:00	S,SEMENI	PT275UN34F2	Montarea prizei de pamint	Bloc locativ
2022-05-11 12:30	2022-05-11 16:00	S,SEMENI	PT104UN34	Reparatia curente	PT-10/0.4 KV
2022-05-13 8:00	2022-05-13 16:00	STR,C PORUMBESCU,DECEBAL	PT13UN30F7	Montarea prizei de pamint	LEA 0.4 KV
2022-05-13 8:00	2022-05-13 16:00	S,TODIRESTI	PT277PR2F3	Strunirea conductorilor	LEA 0.4 KV

