

| Data/ora deconectării | Data/ora conectării | Adresa deconectărilor | Denumirea PT | Denumirea lucrarilor | LEA/PT |
|-----------------------|---------------------|---|--------------|--------------------------------|----------------------|
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Gura Căinarului - fără consumatori casnici | PT34aLN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Prajila | PT69LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Prajila | PT157LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Prajila | PT573LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Lunga | PT451LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Lunga | PT452LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Japca | PT686CG3F1 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Prajila | PT18LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Prajila | PT21LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 12:00 | sat Zahorna | PT810CJ9F1 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Prajila | PT17LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Prajila | PT19LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Prajila | PT20LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Lunga | PT451LN9 | Reparatia curente | PT-10/04(tip inchis) |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Lunga | PT452LN9 | Reparatia curente | PT-10/04(tip inchis) |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Prajila | PT18LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Prajila | PT21LN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 8:00 | 2022-05-16 16:00 | sat Gura Căinarului - fără consumatori casnici | PT34aLN9 | Strunirea conductorilor | LEA 10KV |
| 2022-05-16 12:30 | 2022-05-16 16:00 | sat Recești | PT845CJ9F1 | Curatirea traseului | LEA 0.4 KV |
| 2022-05-17 8:00 | 2022-05-17 12:00 | sat Prodănești | PT866CJ4F1 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Japca | PT686CG3F2 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Tîrgul Vertiujeni | PT773VT13 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Tîrgul Vertiujeni - fără consumatori casnici | PT792VT13 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | or. Mărculești parțial | PT271FR17 | Schimbarea stilpilor | LEA 0.4 KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Tîrgul Vertiujeni - fără consumatori casnici | PT768VT13 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Tîrgul Vertiujeni | PT770VT13 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Tîrgul Vertiujeni | PT772VT13 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Tîrgul Vertiujeni | PT747VT13 | Reparatia curente | PT-10/04(tip inchis) |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Tîrgul Vertiujeni | PT704VT13 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Tîrgul Vertiujeni | PT705VT13 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Tîrgul Vertiujeni | PT714VT13 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-17 8:00 | 2022-05-17 16:00 | sat Tîrgul Vertiujeni | PT715VT13 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-17 12:30 | 2022-05-17 16:00 | sat Domulgeni | PT884CJ4F2 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-18 8:00 | 2022-05-18 12:00 | sat Căpești | PT857CJ4F2 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-18 8:00 | 2022-05-18 16:00 | sat Japca | PT691CG3F1 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-18 8:00 | 2022-05-18 16:00 | or. Mărculești parțial | PT271FR17F3 | Schimbarea stilpilor | LEA 0.4 KV |
| 2022-05-18 8:00 | 2022-05-18 16:00 | or. Florești, str. Gării 1, 2, 3, 4, 5, 6, 7, 8, 10, 11, 12, 13, 15, 17, str. Pieții 1, str. I. Irimița 3, 10 | PT399FR11F1 | Reparatia panoului de evidenta | Bloc locativ |
| 2022-05-18 12:30 | 2022-05-18 16:00 | sat Ștefănești | PT870CJ4F2 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Nimereuca | PT712VT3 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Nimereuca | PT723VT3 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Nimereuca | PT728VT3 | Reparatia curente | PT-10/0.4 KV |

| | | | | | |
|------------------|------------------|--|-------------|--------------------------------|----------------------|
| 2022-05-19 8:00 | 2022-05-19 16:00 | or. Mărculești parțial | PT271FR17F3 | Schimbarea stilpilor | LEA 0.4 KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Japca | PT691CG3F2 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Nimereuca | PT723VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Nimereuca | PT724VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Cerlina | PT725VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Cerlina | PT709VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Nimereuca | PT712VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Zaluceni - fără consumatori casnici | PT713VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Cerlina | PT729VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Nimereuca | PT730VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Nimereuca | PT731VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Zaluceni | PT720VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Zaluceni | PT721VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Zaluceni - fără consumatori casnici | PT722VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Tîrgul Vertiujeni - fără consumatori casnici | PT717VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Zaluceni | PT718VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | fără consumatori | PT719VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Zaluceni - fără consumatori casnici | PT732VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Nimereuca | PT795VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Cerlina | PT726VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Cerlina | PT727VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-19 8:00 | 2022-05-19 16:00 | sat Nimereuca | PT728VT3 | Montarea prizei de pamint | LEA 10KV |
| 2022-05-20 8:00 | 2022-05-20 16:00 | or. Florești, str. M. Viteazul 72 | PT273FR6 | Reparatia panoului de evidenta | Bloc locativ |
| 2022-05-20 8:00 | 2022-05-20 16:00 | or. Florești, str. M. Viteazul 74 | PT273FR6 | Reparatia panoului de evidenta | Bloc locativ |
| 2022-05-20 8:00 | 2022-05-20 16:00 | sat Băhrinești | PT390FR18F1 | Schimbarea stilpilor | LEA 0.4 KV |
| 2022-05-20 8:00 | 2022-05-20 16:00 | or. Florești, str. M. Viteazul 70, 72, 74 | PT273FR6 | Reparatia curente | PT-10/04(tip inchis) |
| 2022-05-20 8:00 | 2022-05-20 16:00 | sat Sănătăuca | PT691CG3F3 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-20 12:30 | 2022-05-20 16:00 | sat Băhrinești | PT103LN3F 3 | Schimbarea stilpilor | LEA 0.4 KV |