

| Data/ora deconectării | Data/ora conectării | Adresa deconectării | Denumirea PT | Denumirea lucrarilor | LEA/PT |
|-----------------------|---------------------|---|--------------|-----------------------------|----------------------|
| 2022-05-23 9:00 | 2022-05-23 12:00 | sat Buciumeni | PT400CP17 | Cerere consumatorului final | LEA 10KV |
| 2022-05-23 9:00 | 2022-05-23 12:00 | sat Buciumeni | PT335CP17 | Cerere consumatorului final | LEA 10KV |
| 2022-05-23 9:00 | 2022-05-23 12:00 | sat Buciumeni | PT337CP17 | Cerere consumatorului final | LEA 10KV |
| 2022-05-23 9:00 | 2022-05-23 12:00 | sat Buciumeni | PT380CP17 | Cerere consumatorului final | LEA 10KV |
| 2022-05-23 8:00 | 2022-05-23 16:00 | sat Bogheni | PT625CT2F1 | Curatirea traseului | LEA 0.4 KV |
| 2022-05-23 8:00 | 2022-05-23 16:00 | or. Ungheni, str. Decebal 113, 115, 117, 117A, 119, 121, 123, 125, 127, str. M. Sadoveanu 52, 52A, 54, 56, 69, 71, 71B, str. M. Viteazul 88, 90, str. T. Arghezi 57, 59, 61, 63, 65, 67, 67A, 69, 70, 70A, 72, 74, 76, 78, str-la M. Sadoveanu 2, 3, 4, 5, 7, 11, 13, 15, str. Scuterniceni 2 | PT73UN26F1 | Schimbarea stilpilor | LEA 0.4 KV |
| 2022-05-23 8:30 | 2022-05-23 12:00 | sat Medeleni | PT206CP14 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-23 8:30 | 2022-05-23 16:00 | sat Frăsinești | PT281VM14F1 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-23 8:30 | 2022-05-23 16:00 | sat Grăseni | PT522PR2F2 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-23 9:30 | 2022-05-23 16:00 | sat Medeleni extravilan | PT374CP14 | Reparatia curente | LEC 0.4 KV |
| 2022-05-23 12:30 | 2022-05-23 16:00 | sat Medeleni | PT112CP14 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-24 8:00 | 2022-05-24 12:00 | or. Ungheni, str. M. Eminescu 55, scara I, II | PT47UN20F11 | Reparatia curente | Bloc locativ |
| 2022-05-24 8:00 | 2022-05-24 16:00 | or. Ungheni, str. M. Viteazul 54, 56, 56A, 58, 58A, 59, 59B, 60, 60A, 61, 62, 63, 63A, 64, 65A, 66-75, 77, 78, 79, 81, 81A, 82, 83, 84, 85, 85A, str. Mărțișor 2, 3, 8, 10, 12, 14, 16, str. Putna 1A, 1B, 1-15, 18, 20, 24, 28A, str. T. Arghezi 43A, 45, 47, 49, 49A, 51, 51A, 52, 52A, 54, 55, 56, 58, 58A, 60, 60A, 62, 62A, 64, 66, 66A, str-la T. Arghezi 35A | PT73UN26F2 | Schimbarea stilpilor | LEA 0.4 KV |
| 2022-05-24 8:30 | 2022-05-24 12:00 | sat Petrești | PT356CP17 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-24 8:30 | 2022-05-24 16:00 | sat Sinești V.N. | PT646CT8F1 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-24 8:30 | 2022-05-24 16:00 | sat Chirileni | PT370CP18F1 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-24 9:30 | 2022-05-24 16:00 | or. Cornești parțial | PT512CT2 | Reparatia curente | PT-10/04(tip inchis) |
| 2022-05-24 12:30 | 2022-05-24 16:00 | sat Petrești | PT155CP17 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-24 12:30 | 2022-05-24 16:00 | or.Ungheni, str. M. Eminescu 55,scara III, IV | PT47UN20F7 | Reparatia curente | Bloc locativ |
| 2022-05-25 8:00 | 2022-05-25 12:00 | sat Petrești | PT109CP17 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-25 8:00 | 2022-05-25 16:00 | o. Ungheni, str. Romană 64 | PT33UN20F11 | Reparatia curente | Bloc locativ |
| 2022-05-25 8:00 | 2022-05-25 16:00 | or. Ungheni, str. M. Viteazul 54, 56, 56A, 58, 58A, 59, 59B, 60, 60A, 61, 62, 63, 63A, 64, 65A, 66-75, 77, 78, 79, 81, 81A, 82, 83, 84, 85, 85A, str. Mărțișor 2, 3, 8, 10, 12, 14, 16, str. Putna 1A, 1B, 1-15, 18, 20, 24, 28A, str. T. Arghezi 43A, 45, 47, 49, 49A, 51, 51A, 52, 52A, 54, 55, 56, 58, 58A, 60, 60A, 62, 62A, 64, 66, 66A, str-la T. Arghezi 35A | PT73UN26F2 | Schimbarea stilpilor | LEA 0.4 KV |
| 2022-05-25 8:00 | 2022-05-25 16:00 | sat Rădeni | PT533PR7 | Reparatia curente | LEA 10KV |
| 2022-05-25 8:00 | 2022-05-25 16:00 | sat Rădeni | PT537PR7 | Reparatia curente | LEA 10KV |
| 2022-05-25 8:30 | 2022-05-25 16:00 | sat Sinești V.N. | PT593CT8F1 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-25 8:30 | 2022-05-25 16:00 | sat Sinești V.N. | PT593CT8F2 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-25 8:30 | 2022-05-25 16:00 | sat Sculeni | PT306GH3F3 | Montarea prizei de pamint | LEA 0.4 KV |
| 2022-05-25 9:30 | 2022-05-25 16:00 | sat Sinești V.N. | PT676CT8 | Reparatia curente | PT-10/04(tip inchis) |
| 2022-05-25 12:30 | 2022-05-25 16:00 | sat Petrești | PT107CP17 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-26 8:00 | 2022-05-26 16:00 | or. Ungheni, str. Națională 10 | PT55UN20F20 | Reparatia curente | Bloc locativ |

| | | | | | |
|------------------|------------------|---|-------------|---|--------------|
| 2022-05-26 8:00 | 2022-05-26 16:00 | or. Ungheni, str. Decebal 113, 115, 117, 117A, 119, 121, 123, 125, 127, str. M. Sadoveanu 52, 52A, 54, 56, 69, 71, 71B, str. M. Viteazul 88, 90, str. T. Arghezi 57, 59, 61, 63, 65, 67, 67A, 69, 70, 70A, 72, 74, 76, 78, str-la M. Sadoveanu 2, 3, 4, 5, 7, 11, 13, 15, str. Scuterniceni 2 | PT73UN26F1 | Montarea prizei de pamint | LEA 0.4 KV |
| 2022-05-26 8:30 | 2022-05-26 12:00 | sat Rădeni | PT534PR7 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Elizavetovcca - fără consumator casnici | PT106UN28 | Strunirea conductorilor | LEA 10KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Elizavetovcca | PT149UN28 | Strunirea conductorilor | LEA 10KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Nicolaevca Nouă | PT162UN28 | Strunirea conductorilor | LEA 10KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Elizavetovcca | PT171UN28 | Strunirea conductorilor | LEA 10KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Elizavetovca - fără consumatori casnici | PT292UN28 | Strunirea conductorilor | LEA 10KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Zagarancea - fără consumatori casnici | PT727UN28 | Strunirea conductorilor | LEA 10KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Todirești - fără consumatori casnici | PT748UN28 | Strunirea conductorilor | LEA 10KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Cornova | PT724CT8F1 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Cornova | PT724CT8F2 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Rădeni | PT648PR7F3 | Montarea conductorilor | LEA 0.4 KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Sculeni | PT306GH3F1 | Montarea prizei de pamint | LEA 0.4 KV |
| 2022-05-26 8:30 | 2022-05-26 16:00 | sat Sculeni | PT306GH3F2 | Montarea prizei de pamint | LEA 0.4 KV |
| 2022-05-26 12:30 | 2022-05-26 16:00 | sat Rădeni | PT537PR7 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Cetireni | PT130DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Untești | PT132DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Untești | PT133DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Untești | PT141DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Cetireni | PT168DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Untești | PT169DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Untești | PT174DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Untești | PT175DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Cetireni | PT195DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Cetireni | PT220DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | fără consumatori casnici | PT361DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | sat Untești | PT707DT8 | Demontarea dupa reconstructie LEA 10/04 | LEA 10KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | or. Ungheni, str. M. Viteazul 54, 56, 56A, 58, 58A, 59, 59B, 60, 60A, 61, 62, 63, 63A, 64, 65A, 66-75, 77, 78, 79, 81, 81A, 82, 83, 84, 85, 85A, str. Mărțișor 2, 3, 8, 10, 12, 14, 16, str. Putna 1A, 1B, 1-15, 18, 20, 24, 28A, str. T. Arghezi 43A, 45, 47, 49, 49A, 51, 51A, 52, 52A, 54, 55, 56, 58, 58A, 60, 60A, 62, 62A, 64, 66, 66A, str-la T. Arghezi 35A | PT73UN26F2 | Montarea prizei de pamint | LEA 0.4 KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | or. Ungheni, Stația Berești | PT96UN28 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-27 8:00 | 2022-05-27 16:00 | or. Ungheni, Stația Berești | PT216UN28 | Reparatia curente | PT-10/0.4 KV |
| 2022-05-27 8:30 | 2022-05-27 16:00 | sat Bumbăta | PT710PR7F1 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-27 8:30 | 2022-05-27 16:00 | sat Bumbăta | PT710PR7F3 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-27 8:30 | 2022-05-27 16:00 | sat Chirileni | PT370CP18F3 | Strunirea conductorilor | LEA 0.4 KV |
| 2022-05-27 8:30 | 2022-05-27 16:00 | sat Sculeni | PT353CP14F3 | Strunirea conductorilor | LEA 0.4 KV |

| | | | | | |
|-----------------|------------------|-------------|----------|-------------------|----------------------|
| 2022-05-27 9:30 | 2022-05-27 16:00 | sat Bumbăta | PT586CT7 | Reparatia curente | PT-10/04(tip inchis) |
| 2022-05-27 9:30 | 2022-05-27 16:00 | sat Bumbăta | PT657CT7 | Reparatia curente | PT-10/04(tip inchis) |
| 2022-05-27 9:30 | 2022-05-27 16:00 | sat Bumbăta | PT666CT7 | Reparatia curente | PT-10/04(tip inchis) |