

Data/ora deconectării	Data/ora conectării	Adresa deconectării	Denumirea PT	Denumirea lucrarilor	LEA/PT
2022-06-07 8:30	2022-06-07 12:00	satul COBANI	PT365CB1F1	Reparatia curente	LEA 0.4 KV
2022-06-07 9:00	2022-06-07 16:00	satul DUȘMANI	PT105GL12F3	Reparatia curente	LEA 0.4 KV
2022-06-07 9:00	2022-06-07 16:00	or. Glodeni, str. Tvardovschi 2, 3, 6, 7, 9-28, 32, str. Saharova 1-4, 6-24, 26, 28, 32, 34, 36, 38, 40, str. P. Rareș 6, str. Livezilor 23, str. Gogol 2, 4, 5, 6, 7, 8, 12, 14, str. D. Cantemir 1-7, 2/2, 9, 10, 12, 13, 14, 15, 16, 43, str. Cehov 1-6, 8-12, 14, 16, 18, 20, 22, 24, 26, str. 31 August 1-8, 10, 11, 13-26	PT72GL11	Reparatia curente	PT-10/04 KV
2022-06-07 12:30	2022-06-07 16:00	satul COBANI	PT365CB1F2	Schimbarea stilpilor	LEA 0.4 KV
2022-06-08 8:30	2022-06-08 12:00	satul PETRUNEA	PT206GL13	Reparatia curente	PT-10/04 KV
2022-06-08 8:30	2022-06-08 12:00	satul BRÎNZENI	PT144CM5F1	Reparatia curente	LEA 0.4 KV
2022-06-08 12:00	2022-06-08 16:00	satul DANU	PT30CM6	Reparatia curente	PT-10/04 KV
2022-06-08 12:00	2022-06-08 16:00	satul DANU	PT30CM6F2	Reparatia curente	LEA 0.4 KV
2022-06-08 12:30	2022-06-08 16:00	satul BRÎNZENI	PT144CM5F2	Reparatia curente	LEA 0.4 KV
2022-06-09 8:30	2022-06-09 12:00	satul BRÎNZENI	PT144CM5F3	Reparatia curente	LEA 0.4 KV
2022-06-09 8:30	2022-06-09 12:00	satul CAMENCA	PT159CM5	Reparatia curente	PT-10/04 KV
2022-06-09 12:30	2022-06-09 16:00	satul BRÎNZENI	PT144CM5F4	Reparatia curente	LEA 0.4 KV
2022-06-09 12:30	2022-06-09 16:00	satul CAMENCA	PT162CM5	Reparatia curente	PT-10/04 KV
2022-06-10 8:30	2022-06-10 12:00	satul CLOCOCENII NOI	PT341BT3F1	Curatirea traseului	LEA 0.4 KV
2022-06-10 9:00	2022-06-10 16:00	satul DUȘMANI	PT108GL12F1	Schimbarea stilpilor	LEA 0.4 KV
2022-06-10 12:00	2022-06-10 16:00	satul SADOVOE	PT440ST6	Reparatia curente	PT-10/04(tip inchis)
2022-06-10 12:30	2022-06-10 16:00	satul CLOCOCENII NOI	PT341BT3F2	Reparatia curente	LEA 0.4 KV