

Data/ora deconectării	Data/ora conectării	Adresa deconectării	Denumirea PT	Denumirea lucrărilor	LEA/PT
2022-08-29 8:00	2022-08-29 16:00	s. Chetrosu	PT541ZG2F1	Reparatia curente	LEA 0.4 KV
2022-08-29 8:00	2022-08-29 16:00	s. Chetrosu	PT541ZG2F2	Reparatia curente	LEA 0.4 KV
2022-08-29 8:00	2022-08-29 16:00	s. Popeștii de Sus	PT205ZG5	Montarea manșoanelor la IEC 10/04 KV	PT-10/0.4 KV
2022-08-29 8:00	2022-08-29 16:00	s. Popeștii de Sus	PT352ZG5	Montarea manșoanelor la IEC 10/04 KV	PT-10/0.4 KV
2022-08-30 8:00	2022-08-30 15:00	s. Hăsnășeni Mare	PT311ND5	Reparatia curente	LEA 0.4 KV
2022-08-30 8:00	2022-08-30 16:00	or. Drochia, str. Gudanov 44	PT348DR30F9	Reparatia curente	PT-10/0.4 KV
2022-08-30 8:00	2022-08-30 16:00	s. Chetrosu	PT545ZG2F1	Reparatia curente	LEA 0.4 KV
2022-08-30 8:00	2022-08-30 16:00	s. Chetrosu	PT545ZG2F2	Reparatia curente	LEA 0.4 KV
2022-09-01 8:00	2022-09-01 16:00	or. Drochia, str. Cuzima Cecal 26,28,30,32, str. 31 August-fără consumatori casnici	PT84DR17F6	Reparatia curente	PT-10/0.4 KV
2022-09-01 8:00	2022-09-01 16:00	s. Hăsnășeni Mare	PT401ND5F2	Reparatia curente	LEA 0.4 KV
2022-09-01 8:00	2022-09-01 16:00	s. Hăsnășeni Mare	PT401ND5F3	Reparatia curente	LEA 0.4 KV
2022-09-01 8:00	2022-09-01 16:00	s. Chetrosu	PT316ZG2F1	Reparatia curente	LEA 0.4 KV
2022-09-02 8:00	2022-09-02 16:00	s. Cotova	PT270ZG18F1	Reparatia curente	LEA 0.4 KV
2022-09-02 8:00	2022-09-02 16:00	s. Cotova	PT270ZG18F2	Reparatia curente	LEA 0.4 KV
2022-09-02 8:00	2022-09-02 12:00	s. Hăsnășeni Mare	PT401ND5F1	Reparatia curente	LEA 0.4 KV
2022-09-02 12:30	2022-09-02 16:00	s. Hăsnășeni Mare-fără consumatori casnici	PT85ND5F1	Reparatia curente	LEA 0.4 KV