

Rezina

| Data/ora deconectarii | Data/ora conectarii | Remarca | Denumirea PT | Denumirea lucrarilor | LEA/PT |
|-----------------------|---------------------|-------------------------------|--------------|----------------------|----------------------|
| 2023-01-16 9:30 | 2023-01-16 16:00 | SATUL SOLONCENI | PT49SL3 | Reparatia curente | LEA 10KV |
| 2023-01-16 9:30 | 2023-01-16 16:00 | SATUL SOLONCENI | PT51SL3 | Reparatia curente | LEA 10KV |
| 2023-01-16 9:30 | 2023-01-16 16:00 | SATUL SOLONCENI | PT376SL3 | Reparatia curente | LEA 10KV |
| 2023-01-16 9:30 | 2023-01-16 16:00 | SATUL SOLONCENI | PT377SL3 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | PARTIAL SATUL PECISTE | PT212IG13 | Reparatia curente | PT-10/04(tip inchis) |
| 2023-01-17 9:00 | 2023-01-17 16:00 | PARTIAL SATUL TAHNAUTI | PT380RZ12F1 | Curatirea traseului | LEA 0.4 KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | PARTIAL SATUL TAHNAUTI | PT380RZ12F2 | Curatirea traseului | LEA 0.4 KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | SATUL LALOVA | PT324SH14 | Reparatia curente | LEA 10KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | PARTIAL SATUL PRIPICENI CURCI | PT290IG13F1 | Curatirea traseului | LEA 0.4 KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | SATUL LALOVA | PT326SH14 | Reparatia curente | LEA 10KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | SATUL LALOVA | PT328SH14 | Reparatia curente | LEA 10KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | SATUL LALOVA | PT331SH14 | Reparatia curente | LEA 10KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | SATUL LALOVA | PT150SH14 | Reparatia curente | LEA 10KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | SATUL LALOVA | PT161SH14 | Reparatia curente | LEA 10KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | SATUL LALOVA | PT322SH14 | Reparatia curente | LEA 10KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | SATUL LALOVA | PT323SH14 | Reparatia curente | LEA 10KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | SATUL LALOVA | PT325SH14 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PARTIAL SATUL LALOVA | PT326SH14F2 | Curatirea traseului | LEA 0.4 KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | REZINA STRADA PACII | PT2CR7 | Reparatia curente | PT-10/0.4 KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PARTIAL SATUL COGJLNICENI | PT234IG10F2 | Curatirea traseului | LEA 0.4 KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PARTIAL SATUL LALOVA | PT326SH14F1 | Curatirea traseului | LEA 0.4 KV |
| 2023-01-20 9:00 | 2023-01-20 16:00 | PARTIAL SATUL GORDINESTI | PT309IG13F1 | Curatirea traseului | LEA 0.4 KV |
| 2023-01-20 9:00 | 2023-01-20 16:00 | REZINA B/L STRADA PIROGOV 3 | PT426CR5F9 | Reparatia curente | Bloc locativ |

Dubăsari

| Data/ora deconectarii | Data/ora conectarii | Remarca | Denumirea PT | Denumirea lucrarilor | LEA/PT |
|-----------------------|---------------------|---------|--------------|----------------------|----------|
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT318CS1014 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT134CS1016 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT281CS1016 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT282CS1016 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT328CS1016 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT339CS1016 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT340CS1016 | Reparatia curente | LEA 10KV |

| | | | | | |
|-----------------|------------------|-----------------|-------------|--|----------|
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT314CS1014 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT315CS1014 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT316CS1014 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT317CS1014 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT479CS1014 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT482CS1014 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT491CS1014 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT597CS1014 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT598CS1014 | Reparatia curente | LEA 10KV |
| 2023-01-17 9:00 | 2023-01-17 16:00 | COSNITA | PT481CS1016 | Reparatia curente | LEA 10KV |
| 2023-01-18 9:00 | 2023-01-18 16:00 | COSNITA PARTIAL | PT282CS1016 | Demontarea dupa reconstructie LEA10/04 | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT8CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT11CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT76CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT273CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT275CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT288CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT291CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT292CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT293CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT296CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT002CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT297CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT322CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT563CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT596CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT136CS1021 | Reparatia curente | LEA 10KV |
| 2023-01-19 9:00 | 2023-01-19 16:00 | PIRITA PARTIAL | PT277CS1021 | Reparatia curente | LEA 10KV |