

Data/ora deconectării	Data/ora conectării	Adresa deconectării	Denumirea PT	Denumirea lucrarilor	LEA/PT
2023-02-27 8:00	2023-02-27 13:00	OR.BRICENI	PT228BR4	Reparatia curente	PT-10/0.4 KV
2023-02-27 8:00	2023-02-27 16:00	S.TREBISAUTI	PT23BR17F3	Curatirea traseului	LEA 0.4 KV
2023-02-27 8:00	2023-02-27 16:00	S.CRIVA	PT300LP9F1	Curatirea traseului	LEA 0.4 KV
2023-02-27 13:00	2023-02-27 16:00	OR.BRICENI	PT73BR4	Reparatia curente	PT-10/0.4 KV
2023-02-28 8:00	2023-02-28 13:00	S.TABANI	PT106BR22	Reparatia curente	PT-10/0.4 KV
2023-02-28 8:00	2023-02-28 16:00	S.COLICAUTI	PT493BR19F2	Curatirea traseului	LEA 0.4 KV
2023-02-28 8:00	2023-02-28 16:00	S.CRIVA	PT300LP9F2	Curatirea traseului	LEA 0.4 KV
2023-02-28 8:00	2023-02-28 16:00	S.TABANI	PT108BR22	Reparatia curente	PT-10/0.4 KV
2023-02-28 13:00	2023-02-28 16:00	S.TABANI	PT107BR22	Reparatia curente	PT-10/0.4 KV
2023-03-02 8:00	2023-03-02 16:00	S.DREPCAUTI	PT338LP9F1	Curatirea traseului	LEA 0.4 KV
2023-03-02 8:00	2023-03-02 16:00	S.LARGA	PT250LG15	Curatirea traseului	LEA 10KV
2023-03-02 8:00	2023-03-02 16:00	S.LARGA	PT270LG15	Curatirea traseului	LEA 10KV
2023-03-02 8:00	2023-03-02 16:00	S.LARGA	PT271LG15	Curatirea traseului	LEA 10KV
2023-03-02 8:00	2023-03-02 16:00	S.LARGA	PT273LG15	Curatirea traseului	LEA 10KV
2023-03-02 8:00	2023-03-02 16:00	S.LARGA	PT286LG15	Curatirea traseului	LEA 10KV
2023-03-02 8:00	2023-03-02 16:00	S.LARGA	PT250LG15	Reparatia curente	PT-10/0.4 KV
2023-03-02 8:00	2023-03-02 16:00	S.LARGA	PT270LG15	Reparatia curente	PT-10/0.4 KV
2023-03-02 8:00	2023-03-02 16:00	S.LARGA	PT271LG15	Reparatia curente	PT-10/0.4 KV
2023-03-02 8:00	2023-03-02 16:00	S.LARGA	PT273LG15	Reparatia curente	PT-10/0.4 KV
2023-03-02 8:00	2023-03-02 16:00	S.LARGA	PT286LG15	Reparatia curente	PT-10/0.4 KV
2023-03-03 8:00	2023-03-03 13:00	S.HALAHORA DE SUS	PT497COL7	Reparatia curente	PT-10/0.4 KV
2023-03-03 8:00	2023-03-03 16:00	S.DREPCAUTI	PT318LP9F1	Curatirea traseului	LEA 0.4 KV
2023-03-03 8:00	2023-03-03 16:00	S.GRIMANCAUTI	PT37BR27F2	Curatirea traseului	LEA 0.4 KV
2023-03-03 13:00	2023-03-03 16:00	S.HALAHORA DE SUS	PT155COL7	Reparatia curente	PT-10/0.4 KV